


ASPECT:
The Airborne Spectral Photometric Environmental Collection Technology (ASPECT) aircraft conducted a screening level assessment to evaluate the unreported or undetected releases of hazardous materials or contaminants at the KMCO Inc. in Crosby, Texas on April 3, 2019 from 9:00 am to 9:40 am. The screening level results from ASPECT were compared to the ASPECT list of Texas Commission on Environmental Quality (TCEQ) short-term Air Monitoring Comparison Values (AMCVs) and found no exceedances of the short-term AMCVs. No chemicals were detected by the ASPECT.

AIR MONITORING:
EPA conducted handheld air monitoring at the KMCO Inc. in Crosby, Texas from April 2, 2019 at 2:15 pm to April 3, 2019 at 12:09 pm at 63 locations. No results above the detection limit have been observed.


Legend

- NON DETECT
- SITE LOCATION
- ~ ASPECT DATA
(No Readings Above Benchmarks)



AIR MONITORING MAP KMCO INC EXPLOSION 16503 RAMSEY RD CROSBY, HARRIS COUNTY, TEXAS

REPORTING PERIOD #02
4/2/2019 1500 - 4/3/2019 1200



For Official Use Only



EPA GIS

Printed: 2:55:02 PM 6/10/2019